



## Overview software releases FSE-R25

Version: 2020/03

Part no.:

Translation of the "Original Dokumentation"

# AMK

**Imprint**

**Name:** PDK\_Freigaben\_FSE-R25

**Version:**

Version	Change	Initials
2020/03	Release added: FSE R25 V1.02 2019/51 (206803)	KoJ/LeS

**Previous version:** -

**Product version:**

Product	Firmware version (AMK part no.)	Hardware version (AMK part no.)
KW-R25-CAN	-	-

**Purpose:** Overview of released software versions of the entered products

**Copyright notice:**

© AMK Arnold Müller GmbH & Co. KG

Any transfer or reproduction of this document, as well as utilisation or communication of its contents, requires express consent. Offenders are liable for the payment of damages. All rights are reserved in the event of the grant of a patent or the registration of a utility model or design.

**Reservation:**

We reserve the right to modify the content of the documentation as well as the delivery options for the product.

**Publisher:**

AMK Arnold Müller GmbH & Co. KG

Gaußstraße 37 - 39

D-73230 Kirchheim/Teck

Germany

Phone: +49 7021/50 05-0

Fax: +49 7021/50 05-176

E-mail: [info@amk-group.com](mailto:info@amk-group.com)

Personally liable shareholder: AMK Verwaltungsgesellschaft mbH, Kirchheim/Teck

Registration court: Stuttgart HRB 231283; HRA 230681

Tax-Idnr.: DE 145912804

**Service:**

Phone: +49 7021/50 05-190, Fax -193

For fast and reliable troubleshooting, you can help us by informing our Customer Service about the following:

- Type plate data for each unit
- Software version
- Device configuration and application
- Type of fault/problem and suspected cause
- Diagnostic messages (error messages)

E-mail: [service@amk-group.com](mailto:service@amk-group.com)

**Internet address:**

[www.amk-group.com](http://www.amk-group.com)

## Display conventions

Display	Meaning
0x	0x followed by a hexadecimal number, e.g. 0x500A
'Name' 'Parameter' 'Diagnostic messages'	e.g.: Calling up the 'Delete PLC programme' function. ID1234 'Parameter text' 1234 'Diagnostic message'
→	Task procedure / operating sequence, e.g. 'Start' → 'All programs' → 'Accessories' → 'Editor'

**Content**

V1.02 2019/51  
V1.01 2017/09

**5**  
**5**

## FSE-R25

Release version	Note	Release date	Part number	Overview of changes
<b>V1.02</b> <b>2019/51</b>		2019/51	207666	<p>Based on firmware FSE R25 V1.01 2017/09 (206803)</p> <p>New:</p> <ul style="list-style-type: none"> <li>• Command 'Clear error' and then switch on the controller enable when the motor is rotating (only with P / Q encoder)</li> </ul> <p>Corrections:</p> <ul style="list-style-type: none"> <li>• CAN messages expanded from 3 to 10 pieces</li> <li>• With firmware V1.01 2017/09 it has been observed occasionally that a system startup has been completed with encoder error 2310 info 1 = 2. This behavior has been solved with firmware V1.02.</li> </ul>
<b>V1.01</b> <b>2017/09</b>		2017/09	206803	<p>Based on firmware FSE R06 1.08 2014/47 (205492)</p> <p>New:</p> <ul style="list-style-type: none"> <li>• Controller card R25 instead of R06</li> <li>• 'Free CAN message configuration' mode</li> </ul> <p>Corrections:</p> <ul style="list-style-type: none"> <li>• -</li> </ul> <p>Notes:</p> <ul style="list-style-type: none"> <li>• Based on the controller card AER25 V2.11 2016/46</li> <li>• A release test was not carried out. Approval is based on successful practical testing.</li> </ul>