



## Overview software releases KE-N02

Version: 2019/27

Part no.:

Translation of the "Original Dokumentation"

# AMK

# Imprint

**Name:** PDK\_Freigaben\_KE-N02

| Version | Change                                          | Initials |
|---------|-------------------------------------------------|----------|
| 2019/27 | Release added:<br>KE-N02 V1.04 2016/35 (206631) | KoJ      |

**Previous version:** 2015/39

| Product                                                    | Firmware version (AMK part no.) | Hardware version (AMK part no.) |
|------------------------------------------------------------|---------------------------------|---------------------------------|
| KEN 5-0N<br>KEN 5-FN<br>KEN 5-S10<br>KEN 20-0N<br>KEN 1-0N | -                               | -                               |

**Purpose:** Overview of released software versions of the entered products

**Copyright notice:** © AMK Arnold Müller GmbH & Co. KG  
Any transfer or reproduction of this document, as well as utilisation or communication of its contents, requires express consent. Offenders are liable for the payment of damages. All rights are reserved in the event of the grant of a patent or the registration of a utility model or design.

**Reservation:** We reserve the right to modify the content of the documentation as well as the delivery options for the product.

**Publisher:** AMK Arnold Müller GmbH & Co. KG  
Gaußstraße 37 - 39  
D-73230 Kirchheim/Teck  
Germany  
Phone: +49 7021/50 05-0  
Fax: +49 7021/50 05-176  
E-mail: [info@amk-group.com](mailto:info@amk-group.com)  
Personally liable shareholder: AMK Verwaltungsgesellschaft mbH, Kirchheim/Teck  
Registration court: Stuttgart HRB 231283; HRA 230681  
Tax-Idnr.: DE 145912804

**Service:** Phone: +49 7021/50 05-190, Fax -193  
For fast and reliable troubleshooting, you can help us by informing our Customer Service about the following:

- Type plate data for each unit
- Software version
- Device configuration and application
- Type of fault/problem and suspected cause
- Diagnostic messages (error messages)

E-mail: [service@amk-group.com](mailto:service@amk-group.com)

**Internet address:** [www.amk-group.com](http://www.amk-group.com)

## Display conventions

| Display               | Meaning                                                                                          |
|-----------------------|--------------------------------------------------------------------------------------------------|
| 0x                    | 0x followed by a hexadecimal number, e.g. 0x500A                                                 |
| 'Name'                | e.g.: Calling up the 'Delete PLC programme' function.                                            |
| 'Parameter'           | ID1234 'Parameter text'                                                                          |
| 'Diagnostic messages' | 1234 'Diagnostic message'                                                                        |
| →                     | Task procedure / operating sequence,<br>e.g. 'Start' → 'All programs' → 'Accessories' → 'Editor' |

Content

|               |   |
|---------------|---|
| V1.04 2016/35 | 5 |
| V1.03 2015/31 | 5 |
| V1.02 2014/38 | 5 |
| V1.01 2014/16 | 6 |
| V1.00 2013/15 | 6 |

## Software release: KE-N02

| Release version                | Note | Release date | Part number | Overview of changes                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |
|--------------------------------|------|--------------|-------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>V1.04</b><br><b>2016/35</b> |      | 2016/35      | 206631      | <p>Base is the firmware KE-N02 V1.03 2015/31 (205825)</p> <p>Corrections:</p> <ul style="list-style-type: none"> <li>• Sporadic mains/phase error when switching on 3-phase devices</li> </ul>                                                                                                                                                                                                                                                                                       |
| Release version                | Note | Release date | Part number | Overview of changes                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |
| <b>V1.03</b><br><b>2015/31</b> |      | 2015/31      | 205825      | <p>Base is the firmware KE-N02 V1.02 2014/38 (205360)</p> <p>New supported devices</p> <ul style="list-style-type: none"> <li>• KEN 20-0N (part no.: 47757)</li> <li>• KEN 1-0N (part no.: 47760)</li> <li>• iSA-MC0-4E0-05 (part no.: 47845)</li> <li>• iSA-MC0-4P0-05 (part no.: 47846)</li> <li>• iSA-MC0-4C0-05 (part no.: 47847)</li> <li>• iSA-MC0-400-05 (part no.: 47844)</li> <li>• Temperature sensing interior</li> <li>• Integration of the iSA functionality</li> </ul> |
| Release version                | Note | Release date | Part number | Overview of changes                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |
| <b>V1.02</b><br><b>2014/38</b> |      | 2014/38      | 205360      | <p>Base is the firmware KE-N02 V1.01 2014/16 (204981)</p> <p>New supported device:</p> <ul style="list-style-type: none"> <li>• KEN 5-S10 (part no.: 47804)</li> </ul>                                                                                                                                                                                                                                                                                                               |

| Release version                | Note                              | Release date | Part number | Overview of changes                                                                                                                                                                                                                 |
|--------------------------------|-----------------------------------|--------------|-------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>V1.01</b><br><b>2014/16</b> |                                   | 2014/16      | 204981      | Base is the firmware KE-N02 V1.00 2013/15 (204439)<br><br>Additional operation with 3 x 230 VAC power supply for: <ul style="list-style-type: none"><li>• KEN 5-0N (part no.: 47409)</li><li>• KEN 5-FN (part no.: 47426)</li></ul> |
| Release version                | Note                              | Release date | Part number | Overview of changes                                                                                                                                                                                                                 |
| <b>V1.00</b><br><b>2013/15</b> | Prototype -<br>Inhouse<br>release | 2013/15      | 204439      | -                                                                                                                                                                                                                                   |